





OTL 23VCOSMA

REVISIONS

| REV | DESCRIPTION | DATE | APPROVED |
|-----|--------------------|--------|-----------|
| -- | ECN 15129, RELEASE | 3/8/07 | DM 3/8/07 |



CAUTION
 THIS ASSEMBLY CONTAINS PARTS SENSITIVE TO DAMAGE BY ELECTRO-STATIC DISCHARGE (ESD). USE ESD PRECAUTIONARY PROCEDURES WHEN TOUCHING, REMOVING OR INSERTING.

| | | | | |
|---------------------|----------------|---|-------------------|-------------------------|
| DRAWN ADAM SIDLE | DATE 3/8/07 |  PHILADELPHIA OPERATIONS 2707 BLACK LAKE PLACE, PHILADELPHIA PA. 19154 (USA) | | |
| CHECKED RAS | DATE 3/8/07 | | | |
| ENGINEERING PR | DATE 3/8/07 | OUTLINE DRAWING VCO IN CONNECTORIZED SMA | | |
| MANUFACTURING | DATE | | | |
| QUALITY DM | DATE 3/8/07 | SIZE A | FSCM NO. 60979 | DWG NO. OTL 23VCOSMA |
| | | K:\ENG\ACL\TWIN\OUTLINE NEW\VCO SMA SHT 1 OF 1 | | |